



Work Report/Time Entry - ACCEPTED

Work Report Location

Search... AliasId.: 052 Type: Signal SR:

Location: SR---SR--- 000.000 ---ts00000 Signal(052) - 17th and Q Ave. *

Documents Tree History New Loc.

Work Report

Crew*	CS	WO#*	Function*	Grp	Units	Reg.	O/T	Call	Cmp.	Adm.	Pen.
Polda, Dave		JA2711	6806	02		10.00	0.00	0.00	0.00	0.00	0.00

Total submitted and held hours for 01/14/2009: 15.00 0.00 0.00 0.00 0.00 0.00

Arrived at: 08:00 on 01/14/2009 * PM Type:

Completed at: 15:00 on 01/14/2009 * Task: * Lct #:

Departed at: 15:00 on 01/14/2009 *

Complete: No *

RFW:

Repair

Action: Loaded material needed to complete repairs to signal after having PSE drop power onto mastarm, downloaded program onto new 2070 controller and conflict monitor. Met Mike and Howard at intersection and began work. Installed new controller and conflict monitor, rewired peds on corner near c Mike and Howard worked overhead on mastarm. Found more damage to both ped modules and audible peds, terminal strips and wiring. Replaced that was damaged and helped pull in new seven conductor for signal displays. Still had problems with ped displays so started replacing this cable als on intersection and found three amber outages and one left turn green. Picked up signs and materials for the day and returned to Mt. Vernon Signals unloaded damaged parts and unused materials.