



City of Anacortes
 904 6th Street
 P.O.Box 547
 Anacortes, WA 98221-0547
 (360) 293-1901

Permit #: BLD-2003-9193
Issue date: 11/07/2003
Expire date: 01/06/2004

Job Address: 1014 25TH ST
 ANACORTES WA.98221

Permit Type: Demolition Permit
Project:

APN: P57315

Remarks: Demolish single family residence.

Owner: JURKOVICH BRANKO

Contractor:

Address:

Address:

Phone:

Phone:

License #:

General Information:

Fees:

Total Calculated:
 Adjustments:
 Deposits/Receipts:
 Total Due:

*3/10/04 BRANKO JURKOVICH called - to withdraw
 this permit - he now has a REVISION...
 Ed J. [Signature]*

THIS PERMIT BECOMES NULL AND VOID IF WORK OR CONSTRUCTION AUTHORIZED IS NOT COMMENCED WITHIN 180 DAYS, OR IF CONSTRUCTION OR WORK IS SUSPENDED OR ABANDONED FOR A PERIOD OF 180 DAYS AT ANY TIME AFTER WORK IS COMMENCED. I HEREBY CERTIFY THAT I HAVE READ AND EXAMINED THIS APPLICATION AND KNOW THE SAME TO BE TRUE AND CORRECT. ALL PROVISIONS OF LAWS AND ORDINANCES GOVERNING THIS TYPE OF WORK WILL BE COMPLIED WITH WHETHER SPECIFIED HEREIN OR NOT, THE GRANTING OF A PERMIT DOES NOT PRESUME TO GIVE AUTHORITY TO VIOLATE OR CANCEL THE PROVISIONS OF ANY OTHER STATE OR LOCAL LAW REGULATING CONSTRUCTION OR THE PERFORMANCE OF CONSTRUCTION.

[Signature]

SIGNATURE OF OWNER OR AUTHORIZED AGENT

[Signature]

ISSUED BY

ATT: EDD. FRANK

**CITY OF ANACORTES
DEMOLITION PERMIT APPLICATION**

Site Address: 1014 25th ST Date: 11-5-2003
Assessors Account No.: 3794-002-007.0003 ; P57315
Lot(s): 5 To 7 Block: 2 Addition: HENSLEY'S 1st TO ANA

Owners Name: BRANKO JURKOVIC
Address: 608 LONGVIEW AVE
State: WA Zip: 98221
Phone: 360-293-6756

Contractors Name: BRANKO BONT
Address: 608 LONGVIEW AVE
State: WA Zip: 98221
Contractors License: 600 4781338
Phone: 360-293-6756

Have Utilities Been Notified?

Water Dept.: Yes No
Electric: Yes No
Cable: Yes No
Gas: Yes No
Phone: Yes No

Describe Work & Tools To Be Used. How Will Materials Be Disposed?

EXCAVATOR - DUMSTER
DONATION TO
KIWANIS TRUST SHOP

**BARRICADES TO BE PROVIDED FOR PUBLIC PROTECTION, AREA MUST BE ROPED OFF!!!!!!!!!!!!!!
SEE SECTION 4409 U.B.C**

Branko Jurkovic
(Applicant's or Agent's Signature)

ASBESTOS WARNING

Breathing asbestos is hazardous to your health. Before starting a renovation or demolition project, survey for friable asbestos materials. Notify Northwest Air Pollution Authority prior to asbestos removal or containment. 201 Pioneer Bldg., Mt. Vernon, WA 98273. (360)428-1617

Fire Department Approval: [Signature] Date: 11-5-03
(Fire Chief or Fire Marshal)

Police Dept. Notification: _____ Date: _____

Public Works Dept: [Signature] Date: 11-5-03
(Speed Garrett)

Comments: _____

Agency Use Only

CASE #: _____

Northwest Air Pollution Authority
 1600 South Second Street
 Mount Vernon, WA 98275-0202
 (360) 428-1617 • Fax: (360) 428-1620
<http://www.nwair.org>
 Instructions for completing this form are on the back.
 Please type or print clearly.

AGENCY USE ONLY
 NAME NUMBER

Application for Resident-Owner Asbestos Project

ENCLOSE \$25 PROCESSING

✓ Clearly print your name and mailing address below

Name: BRANKO JURKOVICH

Address: 608 LONGVIEW AVE

City, State, Zip: ANACORTES 98221

Name of Person Conducting Removal:
BRANKO JURKOVICH

Daytime Ph #: 360 293 6756

Evening Ph. #: ---

Quantity to be removed/encapsulated: _____ (sq. ft.) (Inscr ft. for pipe work only)

Project starting date: 11.1.2003 Completion date: JAN 31. 2004

Is this building scheduled for demolition? Yes No

Site address: **THIS MUST BE COMPLETED** (Attach brief explanation if site address is different from mailing address.)

1014 25th ST, ANACORTES 98221 Snohom

Street City Zip code County

Has material to be removed been sampled and analyzed? Yes No

If No, Please explain _____

Facility type (check all that applies):
 Single Family Two or more units
 Non-Owner Occupied Owner Occupied

Type of material to be removed/encapsulated:
 Cement Asbestos Board Duct/Furnace Wrap Popcorn Ceiling Sheet Vinyl Flooring Vinyl Asbestos Tiles
 Other Pipe Insulation Stucco Boiler Insulation Mag. Pipe Insulation
 Plaster Other (specify) _____

Is removal: Indoors Outdoors

Control measures & Personal Protection Equipment:

Face Respirator Disposable Coveralls Eye Protection Disposable Gloves Wetting
 Rubber Boots Plastic to Contain Debris Wrap & Cut (Pipe Removal) Other (specify) _____

Briefly describe your method of removal: EXCAVATOR, DUMSTER.

Asbestos disposal site: MT. VERNON WASH.



I CERTIFY THAT I AM THE OWNER OF THIS PREMISE AND THAT THE ABOVE INFORMATION IS CORRECT.

Branko Jurkovic
 Signature

10.23.2003
 Date



Waste Shipment Record

Generator	1. Work Site Name and Mailing Address 1014 25th St, Anacortes, WA 98221		Owner's Name Brank Jurkovich	Owner's Phone No. 360-293-6756	
	2. Operator's Name and Address Branko Jurkovich 608 Longview Avr, Anacortes, WA			Operator's Phone No. (360)293-6756	
	3. Waste Disposal Site Name, Mailing Address & Physical Site Location Greater Wenatchee Regional Landfill 191 S Webb Ave, Wenatchee, WA 98802			WDS's Phone No. 509-884-2802	
	4. Name and Address of Responsible Agency DAVE BLAKE, NWAPA 1600 S Second St, Mount Vernon, WA 98273 (360) 428-1617				
	5. Description of Materials CAB		6. Containers No. Type 2 bundles	7. Total Quantity m ³ (yd ³) 0.1 cu yds	
	8. Special Handling Instructions and Additional Information				
	9. OPERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled; and are in all respects in proper condition for transport by highway according to applicable international and government regulations.				
	Printed/Typed Name & Title Branko Jurkovich		Signature 	Month Day Year 11/3/03	
	Environmental Abatement Services Inc, 712 S Spruce Burlington		360-757-1085		
Transporter	10. Transporter 1 (Acknowledgment of Receipt of Materials)				
	Printed/Typed Name & Title D & B Trucking Address 1905 E Lincoln Ave, Tacoma, WA 98421		Signature 	Month Day Year	
			Phone No. 253-383-3860		
	11. Transporter 2 (Acknowledgment of Receipt of Materials)				
Printed/Typed Name & Title Address		Signature Phone No.	Month Day Year		
Disposal Site	12. Discrepancy Indication Space				
	13. Waste Disposal Site Owner or Operator:				
	Certification of Receipt of Asbestos Materials Covered by this Manifest except as noted in Item 12.				
	Printed/Typed Name & Title Address		Signature Phone No.	Month Day Year	

PHILLIPS ENVIRONMENTAL SERVICES

29354 BACUS RD.
SEDRO WOOLLEY, WA 98284

360-854-7900

FAX 360-854-7731

October 22, 2003

Survey No. 03095

Branko Jurkovich
608 Longview Ave.
Anacortes, WA 98221
360-293-6756

RE: **Asbestos Survey: 1014 25th Street, Anacortes, WA 98221**

On October 21, 2003, I inspected a single family residence located at the above referenced address for the purpose of determining the presence or absence of building materials that might contain asbestos.

Title 40 Code of Federal Regulations (40 CFR), subpart M, section 61.141, established the allowable limit of asbestos in building materials at 1% by weight. Materials containing more than 1% asbestos are regulated and must be handled in accordance with Federal, State, and Local regulations.

Surveys are based on 'visible and accessible materials' and although reasonable effort was made to locate and test all suspect materials, some suspect materials may remain hidden in walls or below floor underlayment or other areas until demolition or renovation work makes them accessible. If other suspect materials are discovered during the course of demolition or remodel activities they will require testing prior to continuing work.

Nine bulk samples were collected and subsequently analyzed for asbestos content by Polarized Light Microscopy with Stain Dispersion. **None of the samples were found to contain more than 1% asbestos. However, also observed but not tested is cement asbestos board (CAB) skirting around portions of the base of the building.** This material will require handling/removal by trained asbestos workers (or, in some cases, the homeowner – contact Northwest Air Pollution Authority for permit) prior to any remodeling, renovation, or demolition that will lead to the disturbance or removal of asbestos. Prior to removal of these materials, ten-day notices must be filed with the local Air Pollution Authority and the State Department of Labor & Industries.

This letter along with the attached material list and lab report will comprise the 'Asbestos Survey'. Please call us if you have any questions.

Sincerely,



Dave B. Phillips
AHERA Bldg. Insp.
Cert.# 03-2687 (expires 4-23-04)

enclosure

PHILLIPS ENVIRONMENTAL SERVICES

29534 BACUS RD.
SEDRO WOOLLEY, WA 98284

360-854-7900

FAX 360-854-7731

Client: Branko Jurkovich
608 Longview Ave.
Anacortes, WA 98221
360-293-6756

Asbestos Survey - 1014 25th Street
Anacortes, WA 98221

Survey #: 03095

Survey date: 10-21-03

Homogeneous Material List

Material # & Description	Location (homog. area)	Type	Friab	Cond	Qty.	Sample # & Location (see dwg.)	Asbestos
1 Vinyl tile on vinyl sheet	Kitchen floor, top layers	misc	n	f		1 Kitchen floor	N/D
2 Linoleum	Kitchen floor, below underlay	misc	n	f		2 Kitchen floor	N/D
3 Vinyl tile on leveling compound	Front entry floor	misc	n	f		3 Front entry floor	N/D
4 Vinyl tile on vinyl sheet	Bathroom floor	misc	n	f		4 Bathroom floor	N/D
5 Felt-like material	Upstairs floors	misc	n	f		5 Upstairs bedroom	N/D
6 Acoustical tile	Ceilings	misc	n	f		6 Rear bedroom ceiling	N/D
7 Sheetrock & texture	Bedroom walls	misc	n	f		7 Front bedroom wall	N/D
8 Glazing putty	Windows	misc	n	f		8 Front bedroom window	N/D
9 Asphalt roof w/sand	Roof	misc	n	f		9 Roof	N/D

Note: Also observed but not tested is cement asbestos board (CAB) skirting around portions of the base of the building ~130sf

N/D = None Detected
N/T = Not Tested - previous sample tested positive
Quantities shown are approximate - field verification recommended

Note: Friability assessments were made on these materials in their present undisturbed condition, damage or disturbance of any kind may cause some non-friable materials to become friable.

PHILLIPS ENVIRONMENTAL SERVICES

29354 BACUS RD.
SEDRO WOOLLEY, WA 98284

360-854-7900

FAX 360-854-7731

ASBESTOS BULK SAMPLE ANALYSIS

Client Name: Branko Jurkovich
608 Longview Ave.
Anacortes, WA 98221
360-293-6756

Survey #: 03095

Source of Samples: 1014 25th Street, Anacortes, WA 98221

Date Rec'd: 10-21-03

Analytical Method: Polarized Light Microscopy with Dispersion Staining (PLM-DS Method)

Sample No.: 1	Analysis: Asbestos:	None detected
Lab No.: 19345B		
Location: Kitchen floor, top layers	Other fibers:	Cellulose, Glass
Description: Grey vinyl tile w/clear mastic on tan vinyl sheet w/grey fibrous backing on yellow mastic		
<hr/>		
Sample No.: 2	Analysis: Asbestos:	None detected
Lab No.: 19346B		
Location: Kitchen floor, below underlay	Other fibers:	Cellulose
Description: Green linoleum w/black fibrous backing		
<hr/>		
Sample No.: 3	Analysis: Asbestos:	None detected
Lab No.: 19347B		
Location: Front entry floor	Other fibers:	Cellulose
Description: Green vinyl tile w/clear mastic on white leveling compound		
<hr/>		
Sample No.: 4	Analysis: Asbestos:	None detected
Lab No.: 19348B		
Location: Bathroom floor	Other fibers:	Cellulose, Glass
Description: Green vinyl tile w/clear mastic on off white vinyl sheet w/brown fibrous backing		
<hr/>		
Sample No.: 5	Analysis: Asbestos:	None detected
Lab No.: 19349B		
Location: Upstairs floors	Other fibers:	Cellulose
Description: Tan felt		
<hr/>		
Sample No.: 6	Analysis: Asbestos:	None detected
Lab No.: 19350B		
Location: Rear bedroom ceiling	Other fibers:	Cellulose
Description: Tan acoustical tile		
<hr/>		
Sample No.: 7	Analysis: Asbestos:	None detected
Lab No.: 19351B		
Location: Front bedroom wall	Other fibers:	Cellulose
Description: Sheetrock w/texture		

Analyst: 
Dave B. Phillips

Date: 10-22-03

Samples retained for 2 weeks unless otherwise requested in writing.

Lab results are completely confidential. Written permission is required to release results to another party.

PHILLIPS ENVIRONMENTAL SERVICES

29354 BACUS RD.
SEDRO WOOLLEY, WA 98284

360-854-7900

FAX 360-854-7731

ASBESTOS BULK SAMPLE ANALYSIS

Sample No.: 8	Analysis: Asbestos:	None detected
Lab No.: 19352B		
Location: Rear bedroom west window	Other fibers:	Cellulose
Description: Glazing putty		

Sample No.: 9	Analysis: Asbestos:	None detected
Lab No.: 19353B		
Location: Roof	Other fibers:	Cellulose
Description: Asphalt roofing w/sand		

Analyst:  Date: 10-22-03
Dave B. Phillips

Samples retained for 2 weeks unless otherwise requested in writing.
Lab results are completely confidential. Written permission is required to release results to another party.

ADDRESS 1014-25th Theodore

LEGAL DESCRIPTION Hensler's 1st addition to
Aracenter lot 7~~6~~ Block 2 lots 5, 6 + 7

ASSESSORS ACCOUNT NO. 3794-002-007-0003

PERMIT NO.	DATE	DESCRIPTION	DATE FINALED
1175		fence 4'6"	
047	3-17-72	reside residence	
483	9-14-72	remodel Interior of house	
499		gas piping + furnace	
511	9-26-72	new hot water tank.	
3210		dryer gas	