



City of Anacortes
 904 6th Street
 P.O.Box 547
 Anacortes, WA 98221-0547
 (360) 293-1901

Permit #: BLD-2009-0074
Issue date: 03/09/2009
Expire date: 05/08/2009

Job Address: 705 41ST PL
 ANACORTES WA 98221-3621

Permit Type: Demolition Permit
Project:

APN: P57964

Remarks: Decommission removal of 1 300 gallon heating oil tank

Owner: PANZERO RON

Contractor: ULTRA TANK SERVICES

Address: 1117 3RD ST
 ANACORTES WA 98221-1505

Address: PO BOX 30076
 BELLINGHAM WA 98228-2076

Phone:

Phone: (360) 815-5361

License #: ultratso33ck

General Information:

Fees:


Total Calculated:
 Adjustments:
 Deposits/Receipts:
 Total Due:

THIS PERMIT BECOMES NULL AND VOID IF WORK OR CONSTRUCTION AUTHORIZED IS NOT COMMENCED WITHIN 180 DAYS, OR IF CONSTRUCTION OR WORK IS SUSPENDED OR ABANDONED FOR A PERIOD OF 180 DAYS AT ANY TIME AFTER WORK IS COMMENCED. I HEREBY CERTIFY THAT I HAVE READ AND EXAMINED THIS APPLICATION AND KNOW THE SAME TO BE TRUE AND CORRECT. ALL PROVISIONS OF LAWS AND ORDINANCES GOVERNING THIS TYPE OF WORK WILL BE COMPLIED WITH WHETHER SPECIFIED HEREIN OR NOT, THE GRANTING OF A PERMIT DOES NOT PRESUME TO GIVE AUTHORITY TO VIOLATE OR CANCEL THE PROVISIONS OF ANY OTHER STATE OR LOCAL LAW REGULATING CONSTRUCTION OR THE PERFORMANCE OF CONSTRUCTION.

 SIGNATURE OF OWNER OR AUTHORIZED AGENT

By mail Michelle Deaton

 ISSUED BY



CITY OF ANACORTES DEMOLITION PERMIT APPLICATION

Site Address: 705 41ST PLACE

Assessors Account No.: _____ Date: 3/6/09

Lot(s): _____ Block: _____ Addition: _____

Owners Name: <u>RON PANTERO</u> Address: <u>1117 3RD STREET ANACORTES</u> State: <u>WA</u> Zip: <u>98221</u> Phone: <u>360 293 2992</u>	FAX - <u>360-398-0134</u> Contractors Name: <u>ULTRA TANK SERVICES</u> Address: <u>PO BOX 30096 BELLINGHAM</u> State: <u>WA</u> Zip: <u>98228</u> Contractors License: <u>ULTRATSO330K</u> Phone: <u>360 815 5361</u>
--	--

Have Utilities Been Notified? Water Dept.: <input checked="" type="checkbox"/> Yes <input checked="" type="checkbox"/> No Electric: <input checked="" type="checkbox"/> Yes <input checked="" type="checkbox"/> No Cable: <input checked="" type="checkbox"/> Yes <input checked="" type="checkbox"/> No Gas: <input checked="" type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Description of proposed demolition. How will materials be disposed? <u>DECOMMISSION REMOVAL OF (1)</u> <u>300 GALLON HEATING OIL TANK</u> <u>TANK TO BE TRIAWR NUISED AND RECYCLED</u>
--	---

BARRICADES TO BE PROVIDED FOR PUBLIC PROTECTION, AREA MUST BE ROPED OFF!

Applicant's or Agent's Signature

ASBESTOS WARNING


Breathing asbestos is hazardous to your health. Before starting a renovation or demolition project, survey for friable asbestos materials. Notify Northwest Air Pollution Authority prior to asbestos removal or containment 1600 S. 2nd Street, Mt. Vernon, WA 98273 (360) 428-1617.

Fire Department Approval: _____ Date: _____

Police Dept. Approval: _____ Date: _____

Public Works Department Approval: J. M. B. [Signature] Date: 3/9/09

Comments: _____




SITE MAP FOR: DECOMMISSION REMOVAL OF (1) 300 GALLON HEATING OIL TANK
AT 705 41ST PLACE AMACONTE WA


OWNER: RON PAUTERLO
CONTRACTOR: ULTRA TANK SERVICES

R
A
V
E

41ST PLACE



300 GALLON HEATING OIL TANK
TO BE DECOMMISSIONED



CITY OF ANACORTES DEMOLITION PERMIT APPLICATION

Site Address: 705 41ST PLACE

Assessor's Account No.: _____ Date: 3/6/09

Lot(s): _____ Block: _____ Addition: _____

Owners Name: RON PANTERO
Address: 1117 3RD STREET ANACORTES
State: WA Zip: 98221
Phone: 360 293 2992

Contractors Name: ULTRA TANK SERVICES
Address: PO BOX 30096 BELLINGHAM
State: WA Zip: 98228
Contractors License: ULTRATSO33CK
Phone: 360 815 5361


Have Utilities Been Notified?

Water Dept.: Yes No
Electric: Yes No
Cable: Yes No
Gas: Yes No

Description of proposed demolition. How will materials be disposed?

DECOMMISSION REMOVAL OF (1)
300 GALLON HEATING OIL TANK
TANK TO BE TRIPLE RINSED AND RECYCLED

BARRICADES TO BE PROVIDED FOR PUBLIC PROTECTION, AREA MUST BE ROPEL OFF!


Applicant's or Agent's Signature

ASBESTOS WARNING


Breathing asbestos is hazardous to your health. Before starting a renovation or demolition project, survey for friable asbestos materials. Notify Northwest Air Pollution Authority prior to asbestos removal or containment 1600 S. 2nd Street, Mt. Vernon, WA 98273 (360) 428-1617.

Fire Department Approval:  Date: 3-6-09

Police Dept. Approval: _____ Date: _____

Public Works Department Approval: _____ Date: _____

Comments: _____



Bellingham, WA 1520 S. Walnut St. 98225
 Everett, WA 800.755.0228 • 360.737.3400 • 360.767.1442 fax
 Bellingham, WA 604 Graham Dr. Suite A - 98225
 Mountlake Park, WA 350.671.0600 • 360.671.1577 fax

Hydrocarbon Data Report

Client Name: Ultra Tank Services, Inc.
 PO BOX 30096
 Bellingham, WA 98228

Reference Number: 09-03851
 Project: Tank Bottom
 Report Date: 4/2/09
 Date Received: 3/19/09
 Peer Review:

Sample Description: 705 - 41st Place - Tank Bottom	Sample Date: 3/18/09
Lab Number: 7846	Collected By: Unknown
Date: 3/31/09	Analyzed By: GEB

Parameter	Result	Flag	DF	Cleanup			Units	Method	Batch	Comment
				Level	PQL	MDL				
DIESEL (C12 - C24)	3470		1	2000	65	26	mg/Kg	NWTPH-Dx3E50B	DXS_090310	
HEAVIER OILS (C24)	ND		1	2000	65	40	mg/Kg	NWTPH-Dx3E50B	DXS_090310	

Notation:


ND - A result of "ND" indicates that the compound was not detected above the Lab's Method Reporting Limit - MRL.
 PQL - Practical Quantitation Limit is the lowest level that can be achieved within specified limits of precision and accuracy during routine laboratory operating conditions.
 D.F. - Dilution Factor
 Cleanup Level - The regulatory limit for Method A Cleanup Levels (MTCAL, Chapter 173-340 WAC) continues to be the specification in Appendix A of the 2001
 The Cleanup level for Gasoline Range Organics (GRO) is 100 mg/Kg for gas mixtures without benzene and when the total ethylbenzene, toluene and xylene are less than 1% of the gasoline concentration. The Cleanup level for GRO is 30 mg/Kg for all other mixtures.

If you have any questions concerning this report contact us at the above phone number.

705-41st Place

Centerline of R Ave.

N0°59'02"E - 130.00'




Nail on wood fence

N0°59'02"E - 110.00'

L=63.61'
R=45'
Δ=80°59'27"

N89°42'11"W - 125.08'

S32°30'28"E - 121.56'




REMARKS:

- 1. We found no concrete monuments on the streets as shown on subject plat, only Crane's special markers on the blacktop.
- 2. Found iron pipes within 1 ft. NELY from the NE and NW lot corners.

LEGEND:

- - Iron Pipe (set)
- - Crane's Nail & Flash (fnd)
- - Reference Point



PREPARED FOR: Lester Gohr 705 41st Place Anacortes, Wa. 98221	
SCALE: 1" = 30'	DRAWN BY: JW
DATE: 6-1-78	APPROVED BY: JJV
DESCRIPTION: Lot 7, Plat of Mountain View Park, Vol. 7, Page 77, records of Skagit County, Washington.	
JOHN J. VADAI & ASSOCIATES 2916 Commercial Ave., Anacortes, Wn.	MERIDIAN: Per Plat

Phone: 293-9591

ADDRESS 705 41st

LEGAL DESCRIPTION _____

ASSESSORS ACCOUNT NO. 3805-000-007-0004

PERMIT NO.	DATE	DESCRIPTION	DATE FINALED
4505	10-31-78	5' chain link fence	
1728	7-24-74	Grass furrow	