



Work Report/Time Entry - ACCEPTED

Work Report Location

Search... AliasId.: 052 Type: Signal SR:

Location: SR---SR--- 000.000 ---ts00000 Signal(052) - 17th and Q Ave. *

Documents Tree History New Loc.

Work Report

Crew*	CS	WO#*	Function*	Grp	Units	Reg.	O/T	Call	Cmp.	Adm.	Pen.
McAdams, Mike		JA2711	6806	02		3.00	0.00	0.00	0.00	0.00	0.00

Total submitted and held hours for 12/18/2008: 9.00 0.00 0.00 0.00 0.00 0.00

Arrived at: 09:00 on 12/18/2008 * PM Type:

Completed at: 11:00 on 12/18/2008 * Task: * Lct #:

Departed at: 11:00 on 12/18/2008 *

Complete: No *

RFW:

Repair

Action: Found intersection "Dark", investigated and found several breakers had tripped in controller cabinet. Appears we had a huge power surge or over v utility. Burnt wiring from cabinet to splice chamber on pole near controller cabinet, burnt cabinet wiring and destroyed conflict monitor/controller. Cal need to be replaced so we met with City Engineer who took pictures and started claim against PSE. Advised that we will schedule for replacement a needed materials. Placed stop signs at all approaches and placed in all way flash with exception of the arm near cabinet because of burnt wiring.