



Work Report/Time Entry - ACCEPTED

Work Report Location

Search... Alias\ld.: 052 Type: Signal SR:   
 Location: SR---SR--- 000.000 ---ts000000 Signal(052) - 17th and Q Ave. \*   
 Documents Tree History New Loc.

Work Report

Crew*	CS	WO#*	Function*	Grp	Units	Reg.	O/T	Call	Cmp.	Adm.	Pen.	
McAdams, Mike		JA2711	6806	02		7.00	0.00	0.00	0.00	0.00	0.00	
<b>Total submitted and held hours for 01/09/2009:</b>							9.00	0.00	0.00	0.00	0.00	0.00

Arrived at: 08:00 on 01/09/2009 \* PM Type:   
 Completed at: 14:00 on 01/09/2009 \* Task: \* Lct #:   
 Departed at: 14:00 on 01/09/2009 \*   
 Complete: No \*   
 RFW:

- Repair

Action: Loaded materials in Mt. Vernon to change out controller cabinet at this location. Met Mike on site and removed damaged cabinet, nothing was left to then installed new cabinet and wired in. Left intersection in flash until we get new cabling pulled to damaged corner near cabinet.