



Work Report/Time Entry - ACCEPTED

Work Report Location

Search... AliasId.: 052 Type: Signal SR:

Location: SR---SR--- 000.000 ---ts00000 Signal(052) - 17th and Q Ave. *

Documents Tree History New Loc.

Work Report

Crew*	CS	WO#*	Function*	Grp	Units	Reg.	O/T	Call	Cmp.	Adm.	Pen.
Fox, Howard		JA2711	6806	02		11.00	0.00	0.00	0.00	0.00	0.00

Total submitted and held hours for 01/14/2009: 11.00 0.00 0.00 0.00 0.00 0.00

Arrived at: 08:00 on 01/14/2009 * PM Type:

Completed at: 16:30 on 01/14/2009 * Task: * Lct #:

Departed at: 16:30 on 01/14/2009 *

Complete: No *

RFW:

Repair

Action: Loaded material needed to complete repairs to signal after having PSE drop power onto mast arm. Met Mike and Dave at intersection and began w 7 conductors from splice chamber to heads. Replaced doghouse and through head. Moved street sign on mast arm so telephone cabling was no ru top of sign. Relamped two amber displays on phase 4, one amber ball, amber arrow and green arrow on phase 2. Signal then cycled properly, althou needs to do some work on phase 4 ped. Picked up signs and cones.

TEF Equipment

8420 # (Stores Issues)