



Work Report/Time Entry - ACCEPTED

Work Report Location

Search... Alias\ld.: 052 Type: Signal SR:   
 Location: SR---SR--- 000.000 ---ts000000 Signal(052) - 17th and Q Ave.   
 Documents Tree History New Loc.

Work Report

Crew*	CS	WO#*	Function*	Grp	Units	Reg.	O/T	Call	Cmp.	Adm.	Pen.	
Polda, Dave		JA2711	6806	02		5.00	0.00	0.00	0.00	0.00	0.00	
<b>Total submitted and held hours for 01/02/2009:</b>							9.00	0.00	0.00	0.00	0.00	0.00

Arrived at: 10:30 on 01/02/2009 PM Type:   
 Completed at: 14:30 on 01/02/2009 Task: \* Lct #:   
 Departed at: 14:30 on 01/02/2009   
 Complete: No   
 RFW:

- Repair

Action: Went to intersection to measure mast arm on damaged side of intersection from PSE line. Checked wiring in nearby Type 3 JB and conduit condition to Mt. Vernon to compare arm dimensions and build new controller for intersection. Completed controller conversion and started test in shop.