



Work Report/Time Entry - ACCEPTED

Work Report Location

Search... Alias\ld.: 052 Type: Signal SR:
 Location: SR---SR--- 000.000 ---ts00000 Signal(052) - 17th and Q Ave.
 Documents Tree History New Loc.

Work Report

Crew*	CS	WO#*	Function*	Grp	Units	Reg.	O/T	Call	Cmp.	Adm.	Pen.	
Schartung, Mike		JA2711	6806	02		2.00	0.00	0.00	0.00	0.00	0.00	
Total submitted and held hours for 01/07/2009:							17.00	0.00	2.00	0.00	0.00	0.00

Arrived at: 13:30 on 01/07/2009 PM Type:
 Completed at: 15:30 on 01/07/2009 Task: * Lct #:
 Departed at: 15:30 on 01/07/2009
 Complete: No
 RFW:

- Misc.

Action: Gather up material for Mike McAdams for replacement (repair) of doghouse and a 3 section signal with louvered backplates,plumbizors and visors for Anacortes.Load them into back or Rick's truck to take to Mount Vernon shop tomorrow. Paperwork